



In 4WF this resistor is soldered one position down.

Compared to 4WF camshaft hall sensor pickup

- | | |
|-----------------------|-------------------|
| 1 - 4WF missing | 1 - diode 1n4448 |
| 2 - 4WF missing 9,84K | 2 - 10k |
| 3 - 4WF missing 46,3K | 3 - 47k |
| 4 - same 46,3K | 4 - 47k |
| 5 - 4WF missing | 5 - diode 1n4448 |
| 6 - same 46,3K | 6 - 47k |
| 7 - difference 0,33M | 7 - 330k |
| 8 - same 0,55k | 8 - 550 Ohm |
| 9 - same 0,33k | 9 - 330k |
| 10 - same 9,8k | 10 - 10k |
| 11 - 4WF missing | 11 - diode 1n4448 |
| 12 - difference 2,7k | 12 - 2,7k |
| 13 - same 9,7k | 13 - 10k |
| 14 - moved down 4,7k | 14 - 4,7k |
| 15 - difference 0,33M | 15 - 330k |
| 16 - 4WF missing 1,5k | 16 - 1,5k |